

# 2024 Toyota Hilux

SR GUN126R 4X4 Dual Range

**\$54,788**  
Drive Away



**Enquire Now**

Scan the QR code below  
for more information



|                                                                                                               |                                                                                                                        |                                                                                                                          |                                                                                                                       |
|---------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|
|  Model Year<br><b>2024</b>  |  Transmission<br><b>6 SP Manual</b> |  Body Type<br><b>Dual Cab Utility</b> |  Colour<br><b>Glacier White</b>  |
|  Kilometres<br><b>68401</b> |  Engine<br><b>2.8 L</b>             |  Fuel Type<br><b>Diesel</b>           |  VIN<br><b>MR0KA3CDX01328432</b> |
|  Reg<br><b>2FA2NS</b>       |  Stock<br><b>HU8408</b>             |                                                                                                                          |                                                                                                                       |

Reliable, tough and well cared for — 2024 Toyota Hilux SR Dual Cab 4x4 Manual in excellent condition. One owner with full Toyota service history, fitted towbar and balance of warranty until 2029 — a durable, ready-to-work ute you can trust. Key features:



**Horsham Toyota**  
**Call us on (03) 5381 6111**  
81 Stawell Road, Horsham, VIC, 3400

Every effort has been made to ensure the accuracy of the information above, however, errors may occur.